



# Contact gauge

Version: 2011-01



## mechanical, for welding machines

- pressure range from 0 up to 10 bar
- welding pressure monitoring
- Schweißstart-Freigabe durch voreingestellten Mindestdruck

Order-number: XV0.X0.024.004



## digital, for welding machines

- universal sensor
- one analogue output 0-10 V
- welding pressure monitoring
- Schweißstart-Freigabe durch voreingestellten Mindestdruck
- display:
  1. working pressure
  2. min. pressure
  3. max. pressure

Order-number: XV0.X0.021.005

We reserve the right to make changes which are in the interest of technical progress.

© by WMA Schmidt & Bittner GmbH, Baumwaide 23, D-74360 Illfeld-Auenstein, Tel. +49 7062 9066-0, Fax +49 7062 9066-20  
info@wma-sb.de or wma-sb@t-online.de, <http://www.wma-sb.de>

Contact gauge-1